




CN1(CN1)		CN2(CN2)	
1	V33A	1	V33A
2	V33A	2	V33A
3	V33A	3	GND
4	GND	4	GND
5	GND	5	GND
6	GND	6	RAM0
7	GND	7	RAM1
8	GND	8	RAM2
9	GND	9	RAM3
10	GND	10	RAM4
11	GND	11	RAM5
12	GND	12	RAM6
13	GND	13	RAM7
14	GND	14	GND
15	GND	15	GND
16	GND	16	GND
17	GND	17	RAM9
18	GND	18	RAM10
19	GND	19	RAM11
20	GND	20	RAM12
21	GND	21	RAM13
22	GND	22	RAM14
23	GND	23	RAM15
24	GND	24	GND
25	GND	25	GND
26	GND	26	GND
27	GND	27	GND
28	GND	28	GND
29	GND	29	GND
30	GND	30	GND
31	GND	31	GND
32	GND	32	GND
33	GND	33	GND
34	GND	34	GND
35	GND	35	GND
36	GND	36	GND
37	GND	37	GND
38	GND	38	GND
39	GND	39	GND
40	GND	40	GND
41	GND	41	GND
42	GND	42	GND
43	GND	43	GND
44	GND	44	GND
45	GND	45	GND
46	GND	46	GND
47	GND	47	GND
48	GND	48	GND
49	GND	49	GND
50	GND	50	GND
51	GND	51	GND
52	GND	52	GND
53	GND	53	GND
54	GND	54	GND
55	GND	55	GND
56	GND	56	GND
57	GND	57	GND
58	GND	58	GND
59	GND	59	GND
60	GND	60	GND
61	GND	61	GND
62	GND	62	GND
63	GND	63	GND
64	GND	64	GND
65	GND	65	GND
66	GND	66	GND

BANK Group A		BANK Group B	
IOB0	1	IOB22	75
IOB1	2	IOB23	76
IOB2	3	IOB24	77
IOB3	4	IOB25	78
IOB4	5	IOB26	79
IOB5	6	IOB27	80
IOB6	7	IOB28	81
IOB7	8	IOB29	82
IOB8	9	IOB30	83
IOB9	10	IOB31	84
IOB10	11	IOB32	85
IOB11	12	IOB33	86
IOB12	13	IOB34	87
IOB13	14	IOB35	88
IOB14	15	IOB36	89
IOB15	16	IOB37	90
IOB16	17	IOB38	91
IOB17	18	IOB39	92
IOB18	19	IOB40	93
IOB19	20	IOB41	94
IOB20	21	IOB42	95
IOB21	22	IOB43	96
IOB22	23	IOB44	97
IOB23	24	IOB45	98
IOB24	25	IOB46	99
IOB25	26	IOB47	100
IOB26	27	IOB48	101
IOB27	28	IOB49	102
IOB28	29	IOB50	103
IOB29	30	IOB51	104
IOB30	31	IOB52	105
IOB31	32	IOB53	106
IOB32	33	IOB54	107
IOB33	34	IOB55	108
IOB34	35	IOB56	109
IOB35	36	IOB57	110
IOB36	37	IOB58	111
IOB37	38	IOB59	112
IOB38	39	IOB60	113
IOB39	40	IOB61	114
IOB40	41	IOB62	115
IOB41	42	IOB63	116
IOB42	43	IOB64	117
IOB43	44	IOB65	118
IOB44	45	IOB66	119
IOB45	46	IOB67	120
IOB46	47	IOB68	121
IOB47	48	IOB69	122
IOB48	49	IOB70	123
IOB49	50	IOB71	124
IOB50	51	IOB72	125
IOB51	52	IOB73	126
IOB52	53	IOB74	127
IOB53	54	IOB75	128
IOB54	55	IOB76	129
IOB55	56	IOB77	130
IOB56	57	IOB78	131
IOB57	58	IOB79	132
IOB58	59	IOB80	133
IOB59	60	IOB81	134
IOB60	61	IOB82	135
IOB61	62	IOB83	136
IOB62	63	IOB84	137
IOB63	64	IOB85	138
IOB64	65	IOB86	139
IOB65	66	IOB87	140
IOB66	67	IOB88	141
IOB67	68	IOB89	142
IOB68	69	IOB90	143
IOB69	70	IOB91	144
IOB70	71	IOB92	145
IOB71	72	IOB93	146
IOB72	73	IOB94	147
IOB73	74	IOB95	148
IOB74	75	IOB96	149
IOB75	76	IOB97	150
IOB76	77	IOB98	151
IOB77	78	IOB99	152
IOB78	79	IOB100	153
IOB79	80	IOB101	154
IOB80	81	IOB102	155
IOB81	82	IOB103	156
IOB82	83	IOB104	157
IOB83	84	IOB105	158
IOB84	85	IOB106	159
IOB85	86	IOB107	160
IOB86	87	IOB108	161
IOB87	88	IOB109	162
IOB88	89	IOB110	163
IOB89	90	IOB111	164
IOB90	91	IOB112	165
IOB91	92	IOB113	166
IOB92	93	IOB114	167
IOB93	94	IOB115	168
IOB94	95	IOB116	169
IOB95	96	IOB117	170
IOB96	97	IOB118	171
IOB97	98	IOB119	172
IOB98	99	IOB120	173
IOB99	100	IOB121	174
IOB100	101	IOB122	175



	<p>HuMANDATA LTD. OSAKA JAPAN www.hdl.co.jp/en/(Global) www.hdl.co.jp/(Japan)</p>		Altera MAXII T100 CPLD board Rev3	
			DOC. No.	ACM-005
Date:	25-Jan-2012	10:41:22	File:	ACM005B.sch
			Sheet	1 of 1